

FIG. 16.—This and Figure 17 show a method of boxing G. M. C. chassis for shipment